




# Inspection Report

<b>Report No:</b> 94784	<b>Manufacturer:</b> Unknown Manufacturer	
<b>Tag No:</b> 46913	<b>Size:</b> 9.8m x 4.5m x 8m	
<b>Date:</b> 28 Apr 2022	<b>Type:</b> Slide	
	<b>Serial Number:</b> n/a	

## Automated Test Sheet



Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details		Detail	
Anchor Points	Pass	32	Exits	N/A		Anchor Type		d rings	
Anchor Accessories	Pass	pegs	Exit Markings	N/A		Number of Anchors		32	
<b>Structure</b>			Independent Support	N/A		Open Side Fall-off Height		0.7M	
Seam Security	Pass		Emergency Lighting	N/A		Inside Wall Height		1.4M	
Stitching	Pass	4-5mm	Deflation of the User Area	N/A		Play Area			
Blower Tube	Pass	1.4m, back	<b>Slides</b>			Max User Height		<i>Max No. Users</i>	
Walls & Towers	Pass		Height of Walls	N/A	1.2 enclosed	1.0 metre		6	
Step/Ramp Size	N/A		Run Out	Pass	3.5m	1.2 metre		6	
Grounding	Pass		Clamber Net	Pass	steps	1.5 metre		6	
Sharp Angles	Pass		Slide Sheet	Pass		1.8 metre		6	
Pressure	Pass	4w/inches	<b>Blower</b>						
Fall Off Height	Pass	0.7m	Suitability	Pass		Place of Test		newquay	
Trough Depth	Pass	55/11	Inlet and Outlet Mesh	Pass		<b>Notes:</b>			
Entrapment	Pass		Cable and Plug	Pass					
Stability	Pass		Impeller	Pass					
Deflation/Evacuation	Pass		Return Flap	Pass					
Air Loss	Pass		PAT Test	Pass	27.04.2022				
Markings	Pass		Blower Type		fp5047				
Identification	N/A		Blower Size		2hp				
<b>Materials</b>			<b>Risk Assessment Notes:</b>						
Fabric (Fire)	Pass								
Fabric Strength	Pass								
Zips	Pass	x4							
Thread	Pass								
Ropes	Pass								
Netting	Pass	top							
Windows	Pass	back wall							
Artwork	Pass	digital							

## Annual Test

I certify that the inflatable play equipment identified by means of the PIPA tag attached to the unit (number as above) was tested in accordance with the European Standard BS EN 14960 and

# PASSED

If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by visiting [www.pipa.org.uk](http://www.pipa.org.uk) and entering the tag number shown above. Please report any irregularities using the contact details below.

	<b>Report Expiry Date:</b> 27 Apr 2023
	<b>Inspection Body:</b> Active Inflatables
	<b>Print Name:</b> Darko Budin
	<b>Signature:</b> 

See continuation sheet notes here: [pipa.org.uk/notes/94784](http://pipa.org.uk/notes/94784)