




# Inspection Report

<b>Report No:</b> 215742	<b>Manufacturer:</b> Jumbo Inflatables	
<b>Tag No:</b> 12643	<b>Size:</b> 9.9m x 6m x 5.5m	
<b>Date:</b> 23 Jun 2022	<b>Type:</b> Moonwalk	
	<b>Serial Number:</b> 9218-04	

## Automated Test Sheet


Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details		Detail	
Anchor Points	Pass	37	Exits	Pass		Anchor Type	TRIANGLE		
Anchor Accessories	Pass	pegs	Exit Markings	Pass		Number of Anchors	37		
<b>Structure</b>			Independent Support	Pass		Open Side Fall-off Height	0.2M		
Seam Security	Pass	Webbed	Emergency Lighting	Pass		Inside Wall Height	5M		
Stitching	Pass	5mm	Deflation of the User Area	Pass		Play Area	8.5x7.5m		
Blower Tube	Pass	1.4m, sidex2	<b>Slides</b>			Max User Height	Max No. Users		
Walls & Towers	Pass	enclosed	Height of Walls	Pass	enclosed	1.0 metre	30		
Step/Ramp Size	Pass	1.6m	Run Out	Pass		1.2 metre	22		
Grounding	Pass	100KG	Clamber Net	Pass		1.5 metre	20		
Sharp Angles	Pass	No issue	Slide Sheet	Pass		1.8 metre	0		
Pressure	Pass	1.40kpa	<b>Blower</b>						
Fall Off Height	Pass	0.2	Suitability	Pass		Place of Test	newquay		
Trough Depth	Pass	60/12cm	Inlet and Outlet Mesh	Pass		<b>Notes:</b>			
Entrapment	Pass	No issue	Cable and Plug	Pass					
Stability	Pass	No issue	Impeller	Pass					
Deflation/Evacuation	Pass	13secs	Return Flap	Pass					
Air Loss	Pass	No issue	PAT Test	Pass					
Markings	Pass	Front tube	Blower Type	Chinese					
Identification	Pass	Tube	Blower Size	2hp					
<b>Materials</b>			<b>Risk Assessment Notes:</b>						
Fabric (Fire)	Pass	3sec flame							
Fabric Strength	Pass	Manufacturer							
Zips	Pass	3/flaps							
Thread	Pass	Nylon							
Ropes	Pass	20mm							
Netting	N/A	None							
Windows	Pass	20 clear							
Artwork	Pass	Handpainted							

## Annual Test

I certify that the inflatable play equipment identified by means of the PIPA tag attached to the unit (number as above) was tested in accordance with the European Standard BS EN 14960 and

# PASSED

If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by visiting [www.pipa.org.uk](http://www.pipa.org.uk) and entering the tag number shown above. Please report any irregularities using the contact details below.

<b>A1 Weymouth Bouncy Castles</b>	<b>Report Expiry Date:</b> 22 Jun 2023
	<b>Inspection Body:</b> A1 Weymouth Bouncy Castles
	<b>Print Name:</b> Chris Ball
	<b>Signature:</b> 

See continuation sheet notes here: [pipa.org.uk/notes/215742](http://pipa.org.uk/notes/215742)